

SUBJECT: FILM EVALUATION MISSION S 244A

1. CAMERA B 12 WAS USED IN MISSION SØ44A FLOWN ON 15 MARCH 1964; PROCESSING WAS ACCOMPLISHED BY 25X1A

2. ORIGINAL NEGATIVE:

A. THE NEGATIVES APPEAR TO BE SLIGHTLY OVEREXPOSED AND THE RESOLUTION IS POOR.

B. 9R SIDE: INBOARD ROLLER CHATTER IS PRESENT THROUGHOUT
THE FIRST 540 FRAMES. HEAT SPLICES OCCUR BETWEEN THE FOLLOWING FRAMES:
531/532; 797/798; 1063/1064; 1329/1330; 1339/1340; 1595/1596;
1861/1862; 2127/2128; 2393/2394. THERE ARE EMULSION LIFTS IN
FRAMES 58, 583 AND 899. BLISTERS ARE NOTED IN FRAMES 799, 1598
THROUGH 1609, 2153, 2190, 2339, 2340 AND 2354. THERE IS A REPAIRED
TEAR IN FRAME 2114 AND THE TITLING IS SMEARED IN FRAMES 2111
THROUGH 2120. NUMEROUS PINHOLES ARE NOTED IN FRAMES 1224 THROUGH
1315. FRAME 1400 CONTAINS A MANUFACTURER'S SPLICE.

C. 9L SIDE: A PLUS DENSITY STREAK STARTS IN FRAME 1781,

Approved For Release 2000/04/12. CIA-RDP66B00664R000400120004-0
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

GROUP 7

Approved For Release 2000/04/12 : CIA-RDP66B00664R000400120004-0

PAGE TWO

THREL INCHES FROM THE OUTBOARD EDGE, AND IS PRESENT THROUGHOUT THE BALANCE OF THE MISSION. BLISTERS ARE NOTED IN FRAMES 1820, 1821, 1861 AND 1888. THERE IS A SMALL TEAR IN FRAME 1862 AND A RAGGED TEAR EXTENDING THROUGH FRAMES 1820 AND 1821. FOREIGN MATTER IS NOTED IN FRAMES 1824 AND 1833. THERE IS A MANUFACTURER'S SPLICE IN FRAME 1923. HEAT SPLICES ARE PRESENT BETWEEN THE FOLLOWING FRAMES: 265/266; 797/798; 818/819; 1063/1064; 1329/1330; 1595/1596; 1861/1862; 2127/2128; 2393/2394.

D. BOTH SIDES: THE ENTIRE MISSION WAS FLOWN IN MODE II.

FRAMES THROUGH 43 WERE NOT RECEIVED. THE TITLED FRAMES ARE

NUMBERED 44-2525. THERE ARE NO MAJOR CAMERA MALFUNCTIONS OR

PROCESSING ANOMALIES ON THIS MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS FAIR TO POOR DUE PRIMARILY TO ATMOSPHERICS.

- B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS COVERED 20 PERCENT OF THE MISSION.

END OF MSG